




Infrared Thermographic Report

Location: West Electrical Room
Equipment: Panel H1

Problem: 7
Temp Rise: 15°F



Comment: A phase load side wire lug connection on breaker no. 3.

